

VEHICLE INSPECTION REPORT

BH19SWV

Nissan E-Nv200 80KW ACENTA 40KWH

| Inspection | | Vehicle | | | |
|-----------------|--------------|-------------|-------------------|-----------|-----------|
| Serious Damage? | No | VAT | Plus VAT | | |
| | | V5 | Buyer To Apply | | |
| Details | | | | | |
| Reg. date | 19/08/2019 | VIN | VSKYAAME0U0603863 | CAP Below | £2,675.00 |
| Year | 2019 | Body Style | Panel Van | Gearbox | AUTOMATIC |
| Mileage | 45,862 Miles | MOT Due | Expired | Gears | 1 |
| | Warranted | CAP Clean | £3,800.00 | | |
| Fuel Type | Electric | CAP Average | £3,325.00 | | |
| Colour | WHITE | | | | |

INTERMITTENT BATTERY ISSUE SIDE LOAD DOOR, E/ MIRRORS, DEADLOCKS (WITH KEYS), CHARGING CABLE IN REAR

| Tyres | | | |
|--------------|--|---|--|
| Tyres NSF | | | |
| NSR | | | |
| OSF | | ' | |
| OSR | | | |
| Spare | | | |

Features

- Cruise controlDrivers airbag
- Radio/CDPassenger airbag
- Air conditioningCentral locking
- Front electric windows
- Cloth seat trim

Photos














Commercial Vehicle Auctions Limited












Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bonnet Chipped Multiple Chips



3: Wheel Trim nsf Broken Replace



4: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm



5: Door osr Dented Over 30mm



6: Lamp osr Broken Replace



7: Qtr Panel osr Chipped Multiple Chips



8: Seat Base Cover nsf Soiled Heavy

Interior

Carpet ConditionOKUpholstery ConditionOKSeat ConditionPoorOdour-

| EML light illuminated | OK | Oil warning light illuminated | OK |
|--------------------------|----|-------------------------------------|----|
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |